

FIGURE 1A




FIGURE 1B




FIGURE 1C




FIGURE 2A





FIGURE 2B






FIG 4





Fig 5-



A

Fig 6




Fig 19 >

Posterior of  
Joint




Fig 18




Fig 9




Fig 10

1.(a) # 1791

Untreated area  
cross-section

X 24,000

normal  
appearance of  
collagen fibrils




Figure 11




Figure 12

2.(a) # 1779

Treated,  
surface ~ 2 mm  
deep.  
cross-section

X 24,000

increased diameter  
with loss of distinct  
edges.  
visible fine structures.




Figure 13

2(b). " 1782

Treated,  
surface ~ 2mm deep.  
longitudinal  
X 24,000

loss of cross-  
striations,  
increased fibrils  
diameter




Figure 14

3(a). #1783  
Treated  
 $\approx 3 \sim 5$  mm deep.  
Cross-section  
X24,000




Figure 15

3(b). # 1788

Treated

$\approx 3 \sim 5$  mm deep

longitudinal

X24,000




Figure 16